

Appln. No. 10/005,576
Amdt. dated November 25, 2003
Reply to Office Action of June 11, 2003

IN THE DRAWINGS:

Please substitute the attached new sheets of drawings containing Figures 9-12. In Figures 9, 10 and 11, the holder 7(b) is masked by the workstop 21.